



DATE: <u>2013-</u>09-14

## **USED VEHICLE INSPECTION**

Stock #

YR. 2006 M	MAKE BMW			MODEL 6 Series	CLR Silver Gray Metallic/ Black				6B797685		
VIN# WBSEH93486B797685				<b>ODO</b> 85260				ENGINE SIZE 5.0			
<b>R.O.#</b> 50963				TECH # 17145							
EXTERIOR			NEEDS IMMED.	UNDERHOOD			NEEDS IMMED.	Park Brake Cables Front Brakes	<b>X</b> 4		
General Appearance	INSPCTD	. AIIN.	ATTN.	Fluid Levels	INSPCTD	AIIN.	ATTN.	Rear Brakes	3		
Glass	×			Engine Oil	×			Axles/C.V.S./C.V. Boot	s 🛎		
Lenses	×			Trans. Fluid	×			Fuel Tank & Lines	×		
Mouldings	X			Coolant	×			Brake Lines	×		
Mirrors	X			Power Steering	X			Exhaust System	X		
Weather Stripping	×			Brake	<b>X</b>			Shocks/Struts	X		
Accessories	×			Belts & Hoses	<b>X</b>						
Inspection Date	9/18/2	013		Battery	×			<b>OPERATION &amp;</b>			
Color	Silver	Gray	<u>Metalli</u> c	Leaks	×			<b>ROAD TEST</b>			NEEDS
				<b>Hood Supports</b>	×				INSPCT	NEEDS D. ATTN.	IMMED.
INTERIOR				Air Filter	X			Lights/Turn Sig/Haz	X		
				Radiator	×			Wiper/Washer	×		
General Appearance	X			Specific Gravity				Windows/Locks/Doors	X		
Head Liner	X							Steering Wheel	X		
Sun Roof	×			ON HOIST				Alignment	X		
Visors	×							Drift	X		
Rear View Mirror	X			Wheels	LF_	OK_F	RF <u>OK</u>	A.C/Heater	×		
Pillar Trims	X				LR	OK_I	RROK_	Radio & Accessories	X		
Seat Belts	×							Tune-up/Driveability	X		
Dash	X			Tires	LF	9		Road Test	X		
Gauges/Meters	X				RF	9					
Warning Lights	X				LR	5		OIL FILTER			
Interior Lighting	X				RR	6					
Switches	X			Tire Pressure	×			Oil Filter			
Upholstery	X			Alignment-Visual	×						
Color	Black			Leaks							
				Oil	<b>X</b>						
				Trans.	×						

## **NOTES**

SERIVCES: UCI, STATE INSPECTION, OIL CHANGE, WIPERS, LEFT LICENSE PLATE BULB REPLACED.back up sensors are malfunctioning \$\$645.29

Diff.

Coolant

SIGNATURE -