



DATE: <u>2013-</u>09-14

## **USED VEHICLE INSPECTION**

Stock #

YR. 2006 MA	IAKE BMW			MODEL 6 Series	CLR Silver Gray Metallic/ Black				6B797685		
VIN# WBSEH93486B797685				<b>ODO</b> 85260			ENGINE SIZE				
<b>R.O.#</b> 50963				TECH # 17145							
EXTERIOR			NEEDS IMMED.	UNDERHOOD			NEEDS IMMED.	Park Brake Cables Front Brakes	<b>X</b> 1		
General Appearance	INSPCTD	. AIIN.	ATTN.	Fluid Levels	INSPCTD	AIIN.	ATTN.	Rear Brakes	3		
Glass	×			Engine Oil	×			Axles/C.V.S./C.V. Boot	s 🛎		
Lenses	×			Trans. Fluid	×			Fuel Tank & Lines	×		
Mouldings	×			Coolant	×			Brake Lines	×		
Mirrors	X			Power Steering	×			Exhaust System	X		
Weather Stripping	×			Brake	×			Shocks/Struts	X		
Accessories	×			Belts & Hoses	<b>X</b>						
Inspection Date	9/18/2	2013		Battery	×			<b>OPERATION &amp;</b>			
Color	Silver Gray Metallic			Leaks	×			<b>ROAD TEST</b>			NEEDS
				Hood Supports	X				INSPCT	NEEDS D. ATTN.	S IMMED.
INTERIOR				Air Filter	X			Lights/Turn Sig/Haz	X		
				Radiator	×			Wiper/Washer	×		
General Appearance	X			Specific Gravity				Windows/Locks/Doors	X		
Head Liner	X							Steering Wheel	X		
Sun Roof	×			ON HOIST				Alignment	X		
Visors	×							Drift	X		
Rear View Mirror	X			Wheels	LF_	OK_F	RF_OK_	A.C/Heater	X		
Pillar Trims	X				LR <u></u>	OK	RROK_	Radio & Accessories	×		
Seat Belts	×							Tune-up/Driveability	×		
Dash	X			Tires	LF	9		Road Test	×		
Gauges/Meters	X				RF	9					
Warning Lights	×				LR	5		OIL FILTER			
Interior Lighting	×				RR	6					
Switches	×			Tire Pressure	<b>X</b>			Oil Filter			
Upholstery	×			Alignment-Visual	<b>X</b>						
Color	Black			Leaks							
				Oil	<b>X</b>						
				Trans	X1						

## **NOTES**

SERIVCES: UCI, STATE INSPECTION, OIL CHANGE, WIPERS, LEFT LICENSE PLATE BULB REPLACED.back up sensors are malfunctioning \$\$645.29

Diff. Coolant

SIGNATURE —