



DATE: <u>2013-12-20</u>

USED VEHICLE INSPECTION

Stock #

YR. 2008 MA	AKE AU	ıdi		MODEL Q7		CLR Ice Silver Metallic / Black				8D015044		
VIN# WA1EV94L78D015044				ODO 93073		ENGINE SIZE						
R.O.# 56569				TECH # 17145								
EXTERIOR			NEEDS IMMED.	UNDERHOOD			NEEDS IMMED.	Park Brake Cables Front Brakes	X 1			
General Appearance	INSPCTD	. ATTN.	ATTN.	Fluid Levels	INSPCTD	ATTN.	ATTN.	Rear Brakes	8			
Glass	×	_	_	Engine Oil	Š	_		Axles/C.V.S./C.V. Boot				
Lenses	<u> </u>	_	_	Trans. Fluid	Š	_	_	Fuel Tank & Lines	× <u>×</u>		_	
Mouldings	×	ū	ū	Coolant	<u>~</u>	ū		Brake Lines	×		_	
Mirrors	<u>×</u>	_	_	Power Steering	<u> </u>	ū	_	Exhaust System	×			
Weather Stripping	×			Brake	<u>~</u>			Shocks/Struts	×			
Accessories	×			Belts & Hoses	<u>×</u>							
Inspection Date	12/20/	/2012		Battery	<u>×</u>			OPERATION &				
Color	Ice Sil		etallic	Leaks	×			ROAD TEST			NEEDS	
				Hood Supports	×				INIODOTI	NEEDS	S IMMED.	
INTERIOR				Air Filter	×			Lights/Turn Sig/Haz	INSPETE	J. ALIN.	ATTN.	
				Radiator	×			Wiper/Washer	×			
General Appearance	X			Specific Gravity				Windows/Locks/Doors	×			
Head Liner	×							Steering Wheel	X			
Sun Roof	×			ON HOIST				Alignment	X			
Visors	×							Drift	X			
Rear View Mirror	X			Wheels	LF_	OK_F	RF_OK_	A.C/Heater	X			
Pillar Trims	X				LR	OK_F	RROK_	Radio & Accessories	X			
Seat Belts	×							Tune-up/Driveability	×			
Dash	×			Tires	LF	9		Road Test	×			
Gauges/Meters	×				RF	9						
Warning Lights	×				LR	9		OIL FILTER				
Interior Lighting	×				RR	9						
Switches	×			Tire Pressure	X			Oil Filter				
Upholstery	×			Alignment-Visual	X							
Color	Black			Leaks								
				Oil	×							
				Trans.	×							
				Diff.	×							
				Coolant	X							

NOTES

SIGNATURE —